

CENTRAL INTELLIGENCE AGENCY 25X1 REPORT

CD NO.

NO. OF PAGES 1

NO. OF ENCLS.
(LISTED BELOW)

SUPPLEMENT TO
REPORT NO.

THIS IS UNEVALUATED INFORMATION

1. The Aircraft Plant on the northeastern edge of Chkalov (51-45N, 55-06E), Chkalov Oblast, definitely manufactured wings, fuselages, and other aircraft accessories. [redacted] work was also done on piston engine.

25X1 [redacted] aircraft near the assembly hall and at the airfield, but

The craft observed was believed to be a fighter with a three-bladed propeller and fitted with in-line or radial engine. [redacted] the wire between cockpit and tail assembly was used to operate the rudder assembly. [redacted]

[redacted] This aircraft was flown from the plant.

2. Sheet aluminum arrived at the plant while the aircraft or aircraft accessories were trucked out. Power was supplied to the plant from outside. The plant had a transformer station. The plant was surrounded by a board fence and was guarded by armed factory police.

The plant had a transformer station. The plant was surrounded by a board fence and was guarded by armed factory police.

fence and was guarded by armed factory police.

25X1

[illegible]